Message

From: Davis, Eva [Davis.Eva@epa.gov]

Sent: 11/2/2018 5:35:54 PM

To: d'Almeida, Carolyn K. [dAlmeida.Carolyn@epa.gov]
Subject: FW: ST012 Site Activities and two week look ahead

Note that they plan on starting to mix and inject sulfate the week of 11/11

From: Smallbeck, Donald R. [mailto:donald.smallbeck@woodplc.com]

Sent: Friday, November 02, 2018 12:27 PM

To: 'JERRARD, CATHERINE V CIV USAF HAF AFCEC/CIBW' <catherine.jerrard@us.af.mil>; 'Wayne Miller' <Miller.Wayne@azdeq.gov>; d'Almeida, Carolyn K. <dAlmeida.Carolyn@epa.gov>; Pearson, Stuart C.

<stuart.pearson@woodplc.com>

Cc: d p <DPope@css-dynamac.com>; Davis, Eva <Davis.Eva@epa.gov>; 'MOOK, PHILIP H JR GS-15 USAF AFCEC AFCEC/CIBW' <philip.mook@us.af.mil>; 'Geoff Watkin' <Geoff.Watkin@SpecProSvcs.com>; Nicole Goers <Nicole.Goers@TechLawInc.com>; 'Brasaemle, Karla' <KBrasaemle@TechLawInc.com>; 'Rohrbaugh, Amanda' <ARohrbaugh@TechLawInc.com>; 'Bo Stewart' <bo@praxis-enviro.com>; 'William Hughes'

 $<\!William. Hughes@SpecProSvcs.com">; 'steve@uxopro.com' <\!steve@uxopro.com">; 'Jennings, Eleanor' <\!steve@uxopro.com">; 'Jennings, Eleanor' <\!steve@uxopro.com</steve@uxopro.com</steve@uxopro.com</steve@uxopro.com</steve@uxopro.com</steve@uxopro.com</steve@uxopro.com</steve@uxopro.com</steve@uxopro.com</steve@uxopro.com</steve@uxopro.com</steve@uxopro.com</steve@uxopro.com</steve@uxopro.com</steve@uxopro.com</steve@uxopro.com</steve@uxopro.com</steve@uxopro.com</steve@uxopro.com</steve@uxopro.com</steve@uxopro.com</steve@uxopro.com</steve@uxopro.com</steve@uxopro.com</steve@uxopro.com</steve@uxopro.com</steve@uxopro.com</steve@uxopro.com</steve@uxopro.com</steve@uxopro.com</steve@uxopro.com</td>$

<Eleanor.Jennings@parsons.com>; 'Panzino.Paula@azdeq.gov' <Panzino.Paula@azdeq.gov>

Subject: ST012 Site Activities and two week look ahead

Activities Last Week (10/22-10/26)

- SVE Operation
- LNAPL checks
- Continued extraction and treatment- 28.4* gpm reading, ~8.9 million total gallons treated since start-up of EBR extraction. (*flow meter is being investigated due to reduced readings in last two weeks)
- Continued CZ07 extraction (approximately 53,000 gallons pumped over the last week and 1,250,000 gallons pumped since start up)
- Operating Extraction Wells: CZ07, CZ18, UWBZ22, UWBZ26, UWBZ30, LSZ09, LSZ11, LSZ12, LSZ23, LSZ37, LSZ38, LSZ39,
- Extraction Wells Currently Down: CZ19 (sand in well, well likely compromised), CZ21 (corrosion, repair in progress), UWBZ21 (airline break, repair in progress), UWBZ27(corrosion, repair in progress), LSZ28 (hot, pneumatic pump ordered), LSZ29 (hot, pneumatic pump ordered), UWBZ28/LSZ51 (corrosion, repair in progress)
- Continued planning for relocation of oxidizer from ST035 to ST012 to replace the flame oxidizer
- Pump replacement parts and anodes on order

Activities This Week (10/29-11/2)

- SVE Operation
- LNAPL checks
- Continued extraction and treatment (including CZ07).
- Schedule relocation of ST035 oxidizer to ST012 (subject to coordination with ASU)
- Sulfate mixing and injection tentatively scheduled to start on week of November 11th

Next Week (11/5-11/9)

- SVE Operation
- LNAPL checks
- Continue extraction (including CZ07)
- Pump repairs/replacements (subject to parts availability)
- Provide summary of Pilot Study Implementation modifications
- Prepare for sulfate mixing/injection.

D.R. Smallbeck
Principal Program Manager
Construction Remediation

4600 E. Washington Street, Suite 600, Phoenix, Arizona 85034-1917 D +1.602.733.6040 C +1.707.480.7212 Donald.Smallbeck@ameefw.com

www.woodplc.com

WOOD. Amec Foster Wheeler and Wood Group are now Wood.	

This message is the property of John Wood Group PLC and/or its subsidiaries and/or affiliates and is intended only for the named recipient(s). Its contents (including any attachments) may be confidential, legally privileged or otherwise protected from disclosure by law. Unauthorized use, copying, distribution or disclosure of any of it may be unlawful and is strictly prohibited. We assume no responsibility to persons other than the intended named recipient(s) and do not accept liability for any errors or omissions which are a result of email transmission. If you have received this message in error, please notify us immediately by reply email to the sender and confirm that the original message and any attachments and copies have been destroyed and deleted from your system.

If you do not wish to receive future unsolicited commercial electronic messages from us, please forward this email to: unsubscribe@woodplc.com and include "Unsubscribe" in the subject line. If applicable, you will continue to receive invoices, project communications and similar factual, non-commercial electronic communications.

Please click http://www.woodplc.com/email-disclaimer for notices and company information in relation to emails originating in the UK, Italy or France.

As a recipient of an email from a John Wood Group Plc company, your contact information will be on our systems and we may hold other personal data about you such as identification information, CVs, financial information and information contained in correspondence. For more information on our privacy practices and your data protection rights, please see our privacy notice at https://www.woodplc.com/policies/privacy-notice

